


-1G.1



:<u>1</u>G. 2








FIG. 5





FIG. 6








FIG. 8






FIG. 9

integrated heat quantity control flow chart



٠.٠ <u>.</u>.

FIG. 10



A: polishing cloth surface temperature

B: polishing agent solution return temperature (S₆)

C: polishing agent solution supply temperature (S1)

polishing agent solution supply rate 30 l/min

FIG. 11





FIG. 12



A: polishing cloth surface temperature

B: polishing agent solution supply temperature

C: polishing agent solution return temperature

 $\ensuremath{\mathsf{D}}$: polishing table cooling water supply temperature

E: polishing table cooling water return temperature

FIG. 13




FIG. 14




FIG. 15

integrated heat quantity control flow chart




FIG. 16




FIG. 17




FIG. 18






FIG. 19





20/22





FIG. 22



Doormers.coment

FIG. 23

